



CEE/OP Instruction No.17/2023

No. L.253.AC.136.8

Date 11.12.2023

Sr. DEE /TRO/BB,BSL,NGP
Sr. DME/Fr & Op/ BB
DME/Op/ PA
DME(O&C) SUR

Sub: Side collision and derailment at NTY yard in KGP Div/SER on 09.11.2023
Ref: Railway Board's letter No.2022/Elect(TRS)/113/1(Safety Misc) dated 30.11.2023

There was a side collision and derailment of light engine 28177+28565 WAG7/KGP(D) on 09.11.2023, at Nimpura (NTY) goods yard in Kharagpur Division of South Eastern Railway. During investigation of case by JAG Officers, it was noticed that cab changing procedure was not followed by LP/ALP and also proper securing of loco was not ensured by LP/ALP, causing rolling down of loco and side grazing with 2 HL BCN, resulting in derailment of two wagons.

Railway Board vide above referred letter has instructed to ensure correct cab changing procedure for single /multiple locomotives by running staff and same to be checked during field inspections and strict prompt actions to be taken against concerned staff in case of discrepancies.

In view of above, special safety drive to be launched for 15 days to counsel the crew on the above subject and ambush checks to be carried out to check whether loco running crew is following the proper procedure of loco cab changing in yard/station and securing the loco properly before cab changing.

Compliance of the above instructions may be ensured and report to be submitted in following format:

1. No. of CLI associated in drive:
2. No of ambush checks carried out during drive:
3. No of irregularities noticed during drive:
4. Action taken to rectify irregularities:
5. No. of staff counselled (cadre wise):

11.12.2023

(H.M.Sharma)

Chief Electrical Engineer (Op)

Copy to: PCEE, PCSO: For information please

171
03/11/23

प्र.मु.बि.ईजी का.
म. रे. मुंबई छ.शि.म ट
पंजी संख्या RD-2
दिनांक 05/12/23
e-mail date



CEE/OP



भारत सरकार Government of India
रेल मंत्रालय Ministry of Railways
रेलवे बोर्ड (Railway Board)



No. 2022/Elect(TRS)/113/1(Safety Misc)

New Delhi, Dated : 30.11.2023

General Managers (Elect.)

All Zonal Railways
(incl. KRCL)

Sub : Side Collision & Derailment at NTY yard in KGP Div/SER on 09.11.23
Ref : Secy, Rly Board's note no. 2023/Secy/Bd.Mtg./28 dated 22.11.23

An incident involving the rolling down of multiple locomotives occurred at the Nirpura NTY goods yard (KGP Div of SER) on 09.11.2023. The incident resulted in a side-graze with the BCN wagon, leading to the derailment of two wagons and the locomotive.

The incident was discussed in Board meeting held on 15.11.2023, and it is advised that the 'Protocol for proper handling and taking over at the time of cab change should be enforced and strict prompt DAR action be taken against responsible officials.'

It is, therefore, advised to ensure that the correct cab change procedure are being followed for both single / multiple locomotives by running staff & same to be checked during field inspections and strict prompt actions to be taken against responsible officials in case of discrepancies.

(किशोर वैभव)
30/11/2023

कार्यकारी निदेशक विद्युत अभियांत्रिकी (चल स्टॉक)
फ्लोर सं : 1, कमरा सं : 113, रेलवे बोर्ड
टेली और फैक्स: 011- 23387736
ई मेल: kishore.vaibhav@gov.in

All HOD'S	सभी विभागप्रमुख
CESE	मु. वि. से. इंजी.
CELE	मु. वि. लो. इंजी.
CEDE	मु. वि. वि. इंजी.
CEE/OP	मु. वि. इंजी. / परिचालन
CEGE	मु. वि. सा. इंजी.
CEE/RS	मु. वि. इंजी. / आर.एस.
CEE/EFM	मु. वि. इंजी. / वि. उ. प्र.
CMPE (D)	म. प्र. वि. शा. ई. (डिजेल)
DY. CEE/TRD	उप. मु. वि. इंजी. / टी.आर.डी.
DY. CEE/EMU/MD	उप. मु. वि. इंजी. / इ.यू.पू./मु.यू.पू.
DY. CEE/G/HO	उप. मु. वि. इंजी. / गार्डन/हो.
DY. CEE D&G	उप. मु. वि. इंजी. / डी.ए.ए.जी.
DY. CEE/EM	उप. मु. वि. इंजी. / इ.यू.पू.
DY. CEE/OP	उप. मु. वि. इंजी. / परिचालन
DY. CEE/EMU-1	उप. मु. वि. इंजी. / परिचालन/1
DY. CME (P&F)	उप. मु. वि. इंजी. / पी.ए.एफ.
DY. CME	उप. मु. वि. इंजी. / डिजेल