

Central Railway



Head Quarter's Office Electrical branch
2nd floor, parcel office building,
Chhatrapati Shivaji Maharaj Terminus,
Mumbai.

CEE/OP Instruction No.7/2024

No. L.326.OP./Circulars/Instructions/23

Date: 22.03.2024


Sr. DEE/TRO/BB,BSL,NGP
Sr. DME (Fr & Op) BB
DME(Op) PA
DME(O &C) SUR

Sub: Non-observance of Bell code Signals between Motorman/Loco Pilot and Guards of EMU/MEMU /DEMU

It has been noticed that during working on EMU/MEMU/DEMU, prescribed bell code signals between Motormen/Loco Pilots and Guards as per S.R.4.51 -1 are not being followed, sometimes.

In view of above, Divisions are instructed to counsel all Motormen/Loco Pilots to follow the bell codes as per S.R.4.51-1 and ensure through ambush checks whether Motormen/Loco Pilots are following the prescribed bell code signals, wherever necessary as per S.R.4.51-1.

Treat this matter "As Urgent".

 22.03.2024

(H.M.Sharma)
Chief Electrical Engineer/OP